| SECRET | \$B |
|--|--------------------------|
| IB - 371/63 17 December 1963 Copy / of | } - |
| MEMORANDUM FOR: Chief, Manufacturing and Services Division, ORR | |
| | 5X1 |
| THROUGH : Chief, Requirements Branch, Reconnaissance Group, CGS | , |
| FROM : Chief, CIA/PID (NPIC) | |
| SUBJECT : Various Communist Chinese Cement Plants | |
| REFERENCES : (1) ORR Requirement No. C-RR3-80,780 (2) CIA/PID Project No. C 1613-63 | |
| 2. In answer to the requirement a table titled "Partial Listing of Cement Plants from has been attached. This table lists the plants requested and indicates the information obtained on these plants from 2 | 5x1 5x1 5x1 5x1 |
| on extension should you have any further questions regarding this project. This is considered a completed answer to the requirement. | 5X1 5X1 |
| Enclosures: 1. 7 Annotated Enlargements (CIA/PID/IB-P-801 - 805/63 and 820 - 821/63) 2. 1 Table DDR-DUPE | , |
| | |
| SECRET CROWP 1 Exchalas it or retemptic count is paid. | 5x1 |

| • | Partial Listing of Cement Pla | nts from GRC Missions 176 and 180 | IB - 371/63 Copyof8 |
|--|-------------------------------|---|------------------------|
| Location | Name | <u>Description</u> | . Enlargements |
| Chiang-Shan, Chekiang | Chiang-Shan Cement Plant | This plant appears to have, at least, two exposed rotary kilns and a rail served finished products section. One stack at the plant is smoking and therefore the plant was in operation at the time of photogra It is not possible to determine if the only stack associated with the plant. | CIA/PID/IB-P-820/63 |
| Yung-Teng, Kansu | Yung-Teng, Cement Plant | No smoke can be seen coming from the two stacks associated with this plan but a small amount of dust is rising from the second from the left dust collector. The plant was, therefore probably in partial operation at the | at S |
| Lo-Yang, Honan | Lo-Yang Cement Plant | time of photography. The camera was off over this area. | |
| Lushan, Kiangsi | Lushan Cement Plant | Plant was not covered on this missio | None m. None |
| Liu-Chou, Kwangsi Chuang Autonomous Region | Liu-Chou Cement Plant | The plant was not in operation at the time of photography and no new construction was apparent. The mottled tone of the plant area when compared to coverage seems to indicate the plant is overgrown, possibly from disuse. | CIA/PID/IB-P-801/63 |
| -11.6-10, Awangtung | Ying-Te Cement Plant | Due to poor quality of the coverage of this plant its completion status can not be determined. | CIA/PID/IB-P-802/63 |

SECRET

Approved For Release 2006/06/26 : CIA-RDP78T04743A000300010028

In the second

| Continuation of Partia | SECRET | IB - 371/63 Copyof/ | |
|------------------------|------------------------|--|---|
| Location | Name | Description Enlargements | |
| Canton, Kwangtung | Canton Cement Plant | Smoke can be seen emitting from the stacks associated with the housed kilns and and the exposed kiln. This plant, therefore, appears to have been fully operating | 3 |
| Yung-An, Fukien | Yung-An Cement Plant | at the time of photography. Since this plant has had no major construction activity. However, a few minor buildings have been added and some road changes were observed. The plant did not appear to be operating at the time of photography. | 3 |
| Nan-P'ing, Fukien | Nan-P'ing Cement Plant | Due to cloud cover this plant CIA/PID/IB-P-805/63 was not observed on this Mission | 3 |

GROUP 1
Excluded from aptematic dewagrading and declassification













